



Part Num.	Item Description	UPC#	Qty Packaging	Art
<b>Sink Tailpieces – 1 1/2" X 1 1/2" – Double Ended</b>				
1149RB	22 GA ROUGH BRASS - 12"	0 46224 91831 8	24 BULK	
1149PC	22 GA CHROME PLATED - 12"	0 46224 91830 1	24 BULK	
1148RB	22 GA ROUGH BRASS - 16"	0 46224 91829 5	24 BULK	
1148PC	22 GA CHROME PLATED - 16"	0 46224 91827 1	24 BULK	
1148K	22 GA CHROME PLATED - 16"	0 46224 02053 0	5 BAGGED IN DISPLAY CARTON	
2149PC	20 GA CHROME PLATED - 12"	0 46224 92317 6	24 BULK	
2148RB	20 GA ROUGH BRASS - 16"	0 46224 92316 9	24 BULK	
2148PC	20 GA CHROME PLATED - 16"	0 46224 92314 5	24 BULK	
7149RB	17 GA ROUGH BRASS - 12"	0 46224 70334 1	24 BULK	
7149PC	17 GA CHROME PLATED - 12"	0 46224 93712 8	24 BULK	
7148PC	17 GA CHROME PLATED - 16"	0 46224 93709 8	24 BULK	
7148RB	17 GA ROUGH BRASS - 16"	0 46224 93711 1	24 BULK	
<b>Sink Tailpieces – 1 1/2" X 1 1/2" – Hi Way Insert</b>				
601815ASN	20 GA CHROME PLATED - 1" - THREADED ONE END	0 46224 93427 1	25 BULK	
<b>Sink Tailpieces – 2" x 2" – Flanged</b>				
153PC	17 GA CHROME PLATED - 6"	0 46224 74269 2	25 BULK	
154PC	17 GA CHROME PLATED - 8"	0 46224 71005 9	25 BULK	
155PC	17 GA CHROME PLATED - 12"	0 46224 71006 6	25 BULK	
<b>Sink Funnels</b>				
1172SN	22 GA CHROME PLATED - 8"	0 46224 91860 8	12 BULK	
<b>Branch Tailpieces – 1 1/4" x 1 1/4" – Slip Joint</b>				
50SJRB	22 GA ROUGH BRASS - 6" - 3/4" (7/8" O.D.) BRANCH FOR HOSE AND CLAMP OR SWEAT - BRASS NUT	0 46224 02485 9	25 BOXED	
50SJSN	22 GA CHROME PLATED - 6" - 3/4" (7/8" O.D.) BRANCH FOR HOSE AND CLAMP OR SWEAT - BRASS NUT	0 46224 02545 0	25 BOXED	
40SJCP	17 GA CHROME PLATED - 8" - 3/4" (7/8" O.D.) BRANCH FOR HOSE AND CLAMP OR SWEAT	0 46224 03737 8	48 BAGGED	
40SJRBNN	17 GA ROUGH BRASS - 8" - 3/4" (7/8" O.D.) BRANCH FOR HOSE AND CLAMP OR SWEAT - TPR WASHERS - BRASS NUT	0 46224 03736 1	48 BAGGED	
40SJCPBN	17 GA CHROME PLATED - 8" - 3/4" (7/8" O.D.) BRANCH FOR HOSE AND CLAMP OR SWEAT - BRASS NUT	0 46224 03738 5	48 BAGGED	
<b>Branch Tailpieces – 1 1/4" x 1 1/4" – Threaded One End</b>				
50SN	22 GA CHROME PLATED - 6" - 3/4" (7/8" O.D.) BRANCH FOR HOSE AND CLAMP OR SWEAT	0 46224 70543 7	25 BOXED	